

## EQUIPMENT



- Always read, understand & adhere to label instructions
- Always wear personal protective equipment when recommended
- Always read Safety Data Sheets and risk assessments before commencing task

## PROCESS




1. Put out wet floor sign



2. Dilute Hi-Phos 1:10 with clean water in bucket. For heavy scale use product neat.



3. Apply solution to floor with deck scrub, mop or doodlebug applicator.




4. Allow contact time of upto 15 minutes. Do not allow solution to dry out.



5. Agitate & scrub entire surface with deck scrub or doodlebug.



6. Rinse with clean, fresh water & use squeegee to dry the floor.



7. Repeat application if necessary, if there is heavy scale build up.



8. Tiled floor, showing before and after cleaning.